



NOTE:
 BENTOPRO+ PRODUCTS
 REQUIRE A MINIMUM 85%
 MODIFIED PROCTOR

L:\C:\My Drive\epro Master Folder\Drafting\Details\Transitions\Bentopro+30.143.1 UNDER SLAB ASSEMBLY TRANSITION TO OVEREXCAVATED WALL.dwg [Detail] March 12, 2019 8:21am

UNDERSLAB ASSEMBLY TRANSITION TO OVEREXCAVATED WALL

	SYSTEM NAME	DRAWING NUMBER	
	BENTOPRO+	30.143.1	
	DRAFTER	DATE	
	TSH	03/12/19	

AS A SUPPLIER OF FINISHED PRODUCTS ONLY, EPRO SERVICES, INC. DOES NOT ASSUME RESPONSIBILITY FOR ERRORS IN DESIGN, ENGINEERING OR DIMENSIONS. THE PROJECT TEAM MUST VERIFY ALL DIMENSIONS AND SUITABILITY OF DETAILS. THE PRODUCTS LISTED ARE TRADEMARKS OF EPRO SERVICES, INC.

NTS

PAGE 1 OF 1