



G:\My Drive\Epro Master Folder\Drafting\Details\Underslab\E.Proformance M\15.170.1 UNDERSLAB VAPOR ASSEMBLY REPAIR.dwg [Detail] December 30, 2020 - 11:08am

## UNDERSLAB VAPOR ASSEMBLY REPAIR

|   |                 |                |   |
|---|-----------------|----------------|---|
|  | SYSTEM NAME     | DRAWING NUMBER |  |
|   | E.PROFORMANCE M | 15.170.1       |   |
|   | DRAFTER         | DATE           |   |
|   | RJT             | 12/29/2020     |   |

AS A SUPPLIER OF FINISHED RPRODUCTS ONLY, EPRO SERVICES, INC. DOES NOT ASSUME RESPONSIBILITY FOR ERRORS IN DESIGN, ENGINEERING OR DIMENSIONS. THE PROJECT TEAM MUST VERIFY ALL DIMENSIONS AND SUITABILITY OF DETAILS. THE PRODUCTS LISTED ARE TRADEMARKS OF EPRO SERVICES, INC.

NTS

PAGE 1 OF 1